

NAME OF PROJECT / WORK

RCU5216- Readjustment of LED system runway 05-23 CAT I
Río Cuarto Airport (Córdoba)
(2025)

Country:	Argentina
Location:	Río Cuarto - Córdoba
Duration:	3 months
Contractor:	Aeropuertos Argentina S.A.
Contractor's Address:	Honduras 5663, C1414 CABA
Project/Work start date:	Juny 2025
Project/Work end date:	September 2025

Number of Staff: 11

Relevant staff and positions:



Threshold Lights 05

Eng. Claudio Pariewski	Operations Manager
Eng. Gastón Fratto	Construction Coordinator
Eng. Yoherson Gonzalez	Civil Eng.
Eng. Gabriel Ledezma	Specialist Lighting Engineer
Federico Carabajal	
Ariel Moreno	Site Managers
Francisco Cabrera	
Benjamín Ramírez	Specialized Lighting Officers

Activities carried out:

- Runway edge.
- A-B taxiways-Turning basins at both headlands.
- Thresholds in both headlands.
- Adequacy of the Control and Monitoring System.
- Uninstallation and installation of new equipment in the regulator room.
- Installation of Panel.
- Preparation of trench for cable ducting in SET.
- Insulation testing and replacement of low-insulated wiring in taxi-edge circuits.
- Training of maintenance personnel.

RCU5216- Readjustment of LED system runway 05-23 CAT I
Río Cuarto Airport (Córdoba)

Images of Works:

*Runway Edge Lights**Inset Runway Edge Lights**Taxiway Edge Lights**Runway Edge Lights**Installed Lights Board**Machine trenching for primary cables*